


# Dislocation Models


## Instructions:

- Cut the layout along the outer edge.
- Fold up the layout along the **Thick Black Lines** with the drawings facing outside.
- Use the tab to glue the model together forming the 3-D shapes showing at the corner.

# Edge dislocation



# Screw dislocation



# Mixed dislocation

